

CERTIFICATE OF COMPLIANCE

(Pursuant to Section 53 of the Environmental Management Act)

THIS IS TO CERTIFY that as of the date indicated below, the site identified in Schedule A of this Certificate of Compliance has been satisfactorily remediated to meet the applicable Contaminated Sites Regulation remediation standards.

This Certificate of Compliance is qualified by the requirements and conditions specified in Schedule B.

The substances for which remediation has been satisfactorily completed and for which this Certificate of Compliance is valid are listed in Schedule C.

I have issued this Certificate of Compliance based on a review of relevant information including the documents listed in Schedule D. I, however, make no representation or warranty as to the accuracy or completeness of that information.

A Director may rescind this Certificate of Compliance if requirements and conditions imposed in the Certificate of Compliance are not complied with or any fees payable under Part 4 of the Act or regulations are outstanding.

This Certificate of Compliance should not be construed as an assurance that there are no hazards present at the site.

February 15, 2018

Date Issued

Schedule A

The site covered by this Certificate of Compliance is located at 5832 Trans-Canada Highway, Duncan, British Columbia which is more particularly known and described as:

Lot 1, Section 18, Range 6, Quamichan District, Plan 19936; PID: 003-654-796

The approximate centre of the site using the NAD (North American Datum) 1983 convention is:


Latitude: 48° 46' 56.50" Longitude: 123° 41' 59.00"


February 15, 2018

Date Issued

Peter Kickham

For Director, Environmental Management Act





February 15, 2018

Date Issued

Schedule B

Requirements and Conditions

1. Any changes in land, vapour, or water uses must be promptly identified by the responsible persons in a written submission to the Director. An application for an amendment or new Certificate of Compliance may be necessary. The uses to which this condition applies are described in Schedule C and in the site investigation documents listed in Schedule D.

The documents listed in Schedule D indicate that vapour attenuation factors were applied to meet Contaminated Sites Regulation numerical and risk-based standards at and adjacent to the site. These vapour attenuation factors were selected based on assumptions about the structures, locations and depths of buildings expected at and adjacent to the site. These assumptions include the following:

(a) Future buildings must be slab on grade construction at the site grade as of February 15, 2018.

Any inconsistencies that arise between the structures, locations and depths of proposed or constructed buildings at or adjacent to the site and the range of structures, locations and depths of buildings assumed in the selection of vapour attenuation factors in the documents listed in Schedule D must be promptly identified by the responsible persons in a written submission to the Director. An application for an amendment or new Certificate of Compliance may be necessary.

- 2. The principal risk controls which must be present or implemented and must be maintained at the site include the following:
 - (a) Groundwater from the Site will not be used as drinking water
- 3. If requested by the Director, the responsible persons must provide a signed statement indicating whether the principal risk controls listed in clause 2 of this Schedule have been and continue to be met. This may include providing a signed statement by an Approved Professional.

February 15, 2018
Date Issued

Schedule C

Substances and Uses

Substances remediated in soil for commercial land soil use:

To meet numerical remediation standards:

• LEPHs.

To meet risk-based remediation standards:

- VPHs.
- Benzene, ethylbenzene, toluene, xylene.

Substances remediated in vapour for commercial land vapour use:

To meet numerical remediation standards:

• Hexane and methyl cyclohexane.

To meet risk-based remediation standards:

• Benzene, trichloroethene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, xylenes, mixture, VPHv.

Substances remediated in water for drinking water use:

To meet numerical remediation standards:

- Lead,
- Toluene, xylenes (total),
- Benzo[a]pyrene.

To meet risk-based remediation standards:

- Arsenic,
- Benzene, ethylbenzene.

February 15, 2018
Date Issued

Peter Kickham

For Director, Environmental Management Act

Substances remediated in water for freshwater aquatic life water use:

To meet numerical remediation standards:

- Cadmium, chromium,
- Benzene, ethylbenzene, toluene,
- Anthracene, phenanthrene, pyrene.

To meet risk-based remediation standards:

- VPHw, LEPHw,
- Naphthalene.

Substances remediated in water for irrigation water use:

To meet numerical remediation standards:

• Chromium.

To meet risk-based remediation standards:

• Molybdenum.

Substances remediated in water for no specified water use:

To meet numerical remediation standards:

• EPHw_{C10-C19} and VHw_{C6-C10}.

February 15, 2018

Date Issued

Schedule D

Documents

Document Title	Author / Company	Date
Summary of Site Condition	Jim Laidlaw, Groundstar	October 26, 2017
	Projects Ltd. and Patricia	
	Miller, TAM	
	Environmental Ltd.	
Updated 0.5 km BC Ministry of Environment Site	Erin O'Brien and Dawn	October 26, 2017
Registry Search, Former Service Station, 5832 Trans-	Flotten, Golder	
Canada Highway, Duncan, BC		
Off-site Communication Records – 5832 Trans-Canada	Erin O'Brien and Dawn	October 18, 2017
Highway, Duncan, BC	Flotten, Golder	
Detailed Quantitative Human Health and Ecological	Jennifer Cook and	October 13, 2017
Risk Assessment for the Former Duncan Esso Service	Christine Thomas,	
Station, 5832 Trans-Canada Highway, Duncan, BC	Golder	
Additional Requests for Clarification – Review of	Erin O'Brien and Dawn	October 10, 2017
Documents in Support of Certificate of Compliance,	Flotten, Golder	
Former Service Station, 5832 Trans-Canada Highway,		
Duncan, BC		
Additional Requests for Clarification – Review of	Jim Laidlaw, Groundstar	September 28, 2017
Documents in Support of Certificate of Compliance,	Projects Ltd.	
Former Service Station, 5832 Trans-Canada Highway,		
Duncan, BC		
Re: Protocol 6 Approval Application for the use of a	Heather Osachoff, BC	September 15, 2017
site-specific Vapour Attenuation Factor – 5832 Trans-	MoE	
Canada Highway, Duncan BC. (file 26250/8770; Site		
8770)		
Email correspondence (response) providing additional	Erin O'Brien, Golder	August 21, 2017
information on the soil vapour modeling conducted		
using the Johnson and Ettinger model		
Email correspondence requesting "further clarification	Sydney Love, BC MoE	August 16, 2017
on the applicability of the Johnson and Ettinger model		
at the site"	·	
Review of Documents in Support of Certificate of	Erin O'Brien and Dawn	July 31, 2017
Compliance, Former Service Station, 5832 Trans-	Flotten, Golder	
Canada Highway, Duncan, BC		
Protocol 6 Preapproval, 5832 Trans-Canada Highway,	Mark Newman and	June 12, 2017
Duncan, BC (Site Registry ID: 8770)	Dawn Flotten, Golder	

February 15, 2018
Date Issued

Comments and Questions (Spreadsheet) as part of the	Jim Laidlaw, Groundstar	April 17, 2017
Review of Documents in Support of Certificate of	Projects Ltd.	Apin 17, 2017
Compliance, Former Service Station, 5832 Trans-	Trojects Eta.	
Canada Highway, Duncan, BC		
Stage 1 Update, Stage 2 Preliminary Site Investigation	Erin O'Brien and Dawn	March 17, 2017
and Detailed Site Investigation Former Duncan Esso	Flotten, Golder	Water 17, 2017
Service Station, 5832 Trans-Canada Highway, Duncan,	Tiotien, Golder	
BC, SAP No. 88004890		
Stage 1 Preliminary Site Investigation for the Former	Mark Newman and Mark	December 10, 2015
Duncan Esso Service Station, 5832 Trans-Canada	Adamson Golder	December 10, 2015
Highway, Duncan, BC, SAP No. 88004890	7 Idamson Golder	
Data Report for Former Service Station, 5832 Trans-	Erin O'Brien and Phyllis	July 20, 2015
Canada Highway, Duncan, BC, SAP No. 88004890	Bruleigh, Golder	July 20, 2013
Data Report for Environmental Investigation at Former	Wendy Beairsto and	October 1, 2014
Service Station, 5832 Trans-Canada Highway, Duncan,	Rick Peleshytyk, Golder	0000001, 2014
BC, SAP No. 88004890	rdek i elesifytyk, Golder	
Data Report for Former Service Station, 5832 Trans-	Wendy Beairsto and	March 25, 2013
Canada Highway, Duncan, BC, SAP No. 88004890	Rick Peleshytyk, Golder	Widion 25, 2015
2011 Site Monitoring and Sampling Report, 5832 Trans-	Hanna Musslick and	May 25, 2012
Canada Highway, Duncan, BC, SAP No. 88004890	Rick Peleshytyk Golder	1vidy 23, 2012
2010 Site Monitoring and Sampling Report, 5832 Trans-	Jeff Christie and Rick	August 16, 2011
Canada Highway, Duncan, BC, SAP No. 88004890	Peleshytyk, Golder	71ugust 10, 2011
Interim Monitoring Optimization - 5832 Trans-Canada	Jennifer Young and	June 4, 2010
Highway, Duncan, BC, SAP No. 88004890	Robert McLenehan	, 2010
	Golder	
Groundwater Sampling Report, Former Duncan Esso	Jennifer Young and	December 16, 2009
Service Station, 5832 Trans-Canada Highway, Duncan,	Robert McLenehan,	
BC, SAP No. 88004890	Golder	
Groundwater Sampling Report, 5832 Trans-Canada	Wendy Beairsto and	March 26, 2009
Highway, Duncan, BC	Charito Canero, Golder	
Site Investigation and Remedial Excavation, Former	Nadine Schwager and	June 11, 2008
Duncan Esso, 5832 Island Highway, Duncan, BC	Patricia Carmichael,	
	SNC Lavalin	
Site Monitoring and Sampling Report, Duncan Esso,	Robert Stacey and David	December 19, 2007
5832 Island Highway, Duncan, BC.	Kettlewell, SNC Lavalin	
Site Monitoring Report, Duncan Esso Service Station,	A.P. Michielsen,	February 14, 1992
Duncan, British Columbia	O'Connor	
Subsurface Investigation, Esso Service Station, Duncan,	C.J.M Rostron and R.D.	August 16, 1989
British Columbia	King, O'Connor	

February 15, 2018
Date Issued