Performance Verification Plan

Portion of City of Vancouver Laneway adjacent to 708 E 26th Avenue, Vancouver, BC Site ID: 14671



Prepared for:

Fraser Street Residence GP Inc. 668 – 1199 West Pender Street Vancouver, BC V6E 2R1

Prepared by:

Pottinger Gaherty Environmental Consultants Ltd. #1200 – 1185 West Georgia Street Vancouver, BC V6E 4E6

PGL File: 2554-05.02

March 2015



Table of Contents

1.0	Required Risk Controls	1
2.0	Action Required to Implement Risk Controls	1
3.0	Rationale for selecting Performance Verification Plan Elements	2
4.0	Standard Limitations	2

Performance Verification Plan

Site ID: 14671

Site Location: Portion of City of Vancouver Laneway adjacent to 708 E 26th Avenue, Vancouver,

BC. More particularly described as:

Beginning at the SE corner of LOT A DISTRICT LOT 391 GROUP 1 NEW WESTMINSTER DISTRICT PLAN EPP33192 (PoC)

Thence N 001° 01' 22.57" E 10.244m to p1, Thence S 088° 45' 54.8" E 6.048m to p2 Thence S 001° 02' 02.27" W 14.133m to p3 Thence N 080° 45' 54.8" W 6.048m to p4 Thence N 001° 02' 22.57" E 3.889m to PoC

Risk Control Type: 2

This document is meant to satisfy the reporting requirements for Type 2 risk controls as outlined in Contaminated Sites Regulation *Administrative Guidance 14.* Specifically, this document outlines the Performance Verification Plan for implementing the institutional risk management measures described below.

1.0 REQUIRED RISK CONTROLS

The following institutional risk controls are required at the site:

- a) Groundwater wells intended to supply potable water must not be installed at the site; and
- b) A health and safety plan must be implemented for utility workers during excavations or trench work beneath the pavement, including measures to mitigate or eliminate potential exposure to contaminant vapours (such as personal protective equipment).

2.0 ACTION REQUIRED TO IMPLEMENT RISK CONTROLS

The following measures are required to implement risk controls:

- Mandatory communication with the site owner/operator to ensure that groundwater wells intended to supply potable water are not installed; and
- b) Mandatory communication with the site owner/operator to ensure that a health and safety plan is implemented during subsurface activities (excavations and/or trenches) beneath the pavement.

Records of these performance verification actions should be maintained by the responsible person to be submitted to the Ministry of Environment, if requested.



The Director must be notified promptly by the persons responsible for the site if performance verification actions indicate that any required institutional controls are not being met. The following information must be submitted to the Director with the notification, or as soon as practicable thereafter:

- 1. The time period over which institutional controls did not meet the requirements;
- 2. The nature of the excursions;
- 3. The temporary or permanent corrective measures implemented or to be implemented;
- 4. An implementation schedule; and
- 5. Supporting documentation.

3.0 RATIONALE FOR SELECTING PERFORMANCE VERIFICATION PLAN ELEMENTS

- a) Contamination remains in place in soil exceeding the Contaminated Sites Regulation Schedule 5 Residential Land Use Standard protective for drinking water use and in groundwater exceeding the Contaminated Sites Regulation Schedule 6 Drinking Water Standards. Regular inspection to ensure that the site does not have a drinking well installed is not required because:
 - i. The site is municipal laneway and will be for the foreseeable future.
 - ii. The future use of the site is unlikely to change, and therefore would not need a drinking water well.
- b) Unacceptable risk levels associated with inhalation cis-1,2-dichloroethene, trichloroethene, vinyl chloride were identified in PGL's Risk Assessment Report dated March 2015.

4.0 STANDARD LIMITATIONS

PGL prepared this report for Fraser Street Residences GP Inc. and its agents exclusively. It may be relied upon by these parties, the BC Ministry of Environment and the Contaminated Sites Approved Professionals Society exclusively. PGL accepts no responsibility for any damages that may be suffered by third parties as a result of decisions or actions based on this report.

The purpose of the Performance Verification Plan is to provide the client and the Ministry of Environment with the steps necessary to implement and maintain the recommended risk management measures at the site. These recommendations are based on information collected during PGL's environmental investigations. These investigations consisted of a screening for potential contamination and, as is true for all environmental investigations, potential remains for the presence of unknown, unidentified, or unforeseen surface or subsurface contamination. More or different investigation may be required, and additional risk management measures may be required if other risks are identified. The data used to develop these risk management measures is valid for the date of sampling, but site conditions may change with time.

The findings and conclusions are site-specific and were developed in a manner consistent with that level of care and skill normally exercised by environmental professionals currently practicing under similar conditions in the area. Changing assessment techniques, regulations, and site conditions means that environmental investigations and their conclusions can quickly become dated, so this report is for use now.



PGL File: 2554-05.02

The project has been conducted according to our instructions and work program. Additional conditions and limitations on our liability are set forth in our work program/contract. This report is neither an endorsement nor a condemnation of the subject property. No warranty, expressed or implied, is made.

RONMENTAL CONSULTANTS LTD.

Respectfully submitted,

POTTINGER GAHEROVEN

Per:

2748 Cory Nelson

Gory Nelson, B.Se., P

Environmental Scientist

Keith H. Gagné, B.A.S

Senior Environmental En

CPN/KHG/mlo

X:\2500-2599\2554 - Vancouver Pacific Development Corporation\05-02\Client Docs\Roster Docs\COV Lane\r-2554-05-02-PVP COV Lane-Mar15.docx