## **Performance Verification Plan**

# Portion of Fraser Street adjacent to 708 26<sup>th</sup> Street, Vancouver, BC Site ID: NA



Prepared for:

Fraser Street Residence GP Inc. 668 – 1199 West Pender Street Vancouver, BC V6E 2R1

Prepared by:

Pottinger Gaherty Environmental Consultants Ltd. #1200 – 1185 West Georgia Street Vancouver, BC V6E 4E6

PGL File: 2554-05.02

March 2015



### **Table of Contents**

1.0	Required Risk Controls	1
2.0	Action Required to Implement Risk Controls	1
3.0	Rationale for selecting Performance Verification Plan Elements	2
4.0	Standard Limitations	2

#### **Performance Verification Plan**

Site ID: NA

Site Location: Portion of Fraser Street adjacent to 708 Fraser Street, Vancouver, BC. More particularly described as:

Beginning at the SW corner of LOT A DISTRICT LOT 391 GROUP 1 NEW WESTMINSTER DISTRICT PLAN EPP33192 (PoC)

Thence N 068° 10' 02.96" W 20.353m to p1,

Thence N 000° 15' 55.09" E 7.751to p2,

Thence N 069° 30' 44.40" E 20.566m to p3,

Thence S 001° 02' 11.60" W 22.522m to PoC.

Risk Control Type: 2

This document is meant to satisfy the reporting requirements for Type 2 risk controls as outlined in Contaminated Sites Regulation *Administrative Guidance 14.* Specifically, this document outlines the Performance Verification Plan for implementing the institutional risk management measures described below.

#### 1.0 REQUIRED RISK CONTROLS

The following institutional risk controls are required at the site:

a) Groundwater wells intended to supply potable water must not be installed at the site.

#### 2.0 ACTION REQUIRED TO IMPLEMENT RISK CONTROLS

The following measures are required to implement risk controls:

a) Mandatory communication with the site owner/operator to ensure that groundwater wells intended to supply potable water are not installed.

Records of these performance verification actions should be maintained by the responsible person to be submitted to the Ministry of Environment, if requested.

The Director must be notified promptly by the persons responsible for the site if performance verification actions indicate that any required institutional controls are not being met. The following information must be submitted to the Director with the notification, or as soon as practicable thereafter:

- 1. The time period over which institutional controls did not meet the requirements;
- 2. The nature of the excursions;
- 3. The temporary or permanent corrective measures implemented or to be implemented:
- 4. An implementation schedule; and
- 5. Supporting documentation.



PGL File: 2554-05.02

## 3.0 RATIONALE FOR SELECTING PERFORMANCE VERIFICATION PLAN ELEMENTS

- a) Contamination remains in place in soil exceeding the Contaminated Sites Regulation Schedule 5 Residential Land Use Standard protective for drinking water use and in groundwater exceeding the Contaminated Sites Regulation Schedule 6 Drinking Water Standards. Regular inspection to ensure that the Site does not have a drinking well installed is not required because:
  - i. The site is municipal road and sidewalk and will be for the foreseeable future.
  - The future use of the site is unlikely to change, and therefore would not need a drinking water well.

#### 4.0 STANDARD LIMITATIONS

PGL prepared this report for Fraser Street Residences GP Inc. and its agents exclusively. It may be relied upon by these parties, the BC Ministry of Environment and the Contaminated Sites Approved Professionals Society exclusively. PGL accepts no responsibility for any damages that may be suffered by third parties as a result of decisions or actions based on this report.

The purpose of the Performance Verification Plan is to provide the client and the Ministry of Environment with the steps necessary to implement and maintain the recommended risk management measures at the site. These recommendations are based on information collected during PGL's environmental investigations. These investigations consisted of a screening for potential contamination and, as is true for all environmental investigations, potential remains for the presence of unknown, unidentified, or unforeseen surface or subsurface contamination. More or different investigation may be required, and additional risk management measures may be required if other risks are identified. The data used to develop these risk management measures is valid for the date of sampling, but site conditions may change with time.

The findings and conclusions are site-specific and were developed in a manner consistent with that level of care and skill normally exercised by environmental professionals currently practicing under similar conditions in the area. Changing assessment techniques, regulations, and site conditions means that environmental investigations and their conclusions can quickly become dated, so this report is for use now.

The project has been conducted according to our instructions and work program. Additional conditions and limitations on our liability are set forth in our work program/contract. This report is neither an endorsement nor a condemnation of the subject property. No warranty, expressed or implied, is made.

X:\2500-2599\2554 - Vancouver Pacific Development Corporation\05-02\Client Docs\Roster Docs\COV Fraser Street\r-2554-05-02-PVP COV Fraser St-Mar15.docx

