

CERTIFICATE OF COMPLIANCE

(Pursuant to Section 53 of the *Environmental Management Act*)

THIS IS TO CERTIFY that as of the date indicated below, the site identified in Schedule A of this Certificate of Compliance has been satisfactorily remediated to meet the applicable Contaminated Sites Regulation remediation standards and criteria.

This Certificate of Compliance is qualified by the requirements and conditions specified in Schedule B.

The substances for which remediation has been satisfactorily completed and for which this Certificate of Compliance is valid are listed in Schedule C.

I have issued this Certificate of Compliance based on a review of relevant information including the documents listed in Schedule D. I, however, make no representation or warranty as to the accuracy or completeness of that information.

A Director may rescind this Certificate of Compliance if requirements and conditions imposed in the Certificate of Compliance are not complied with or any fees payable under Part 4 of the Act or regulations are outstanding.

This Certificate of Compliance should not be construed as an assurance that there are no hazards present at the site.

May 1, 2019
Date Issued

Liliana Jerade

Schedule A

The site covered by this Certificate of Compliance is located at the west portion of civic address 1579 Kingsway Avenue, Port Coquitlam, British Columbia which is more particularly known and described as:

West portion of Lot A, District Lot 288 and 382, Group 1 and of Section 7, Block 6 North, Range 1 East, New Westminster District, Plan EPP74940, PID: 030-571-791, which may be more particularly described as follows:

Commencing from the southwest corner of Lot A (the point of beginning), thence northerly along the bearing 32°46′50" a distance of 263.003 metres;

Thence easterly along the bearing 122°43'54" a distance of 82.309 metres;

Thence southerly along the bearing 212°46′50" a distance of 263.051 metres;

Thence westerly along the bearing 302°45'55" a distance of 82.309 metres to the point of beginning.

This site contains parts of a legal parcel depicted in an engineering drawing prepared by Hemmera Envirochem Inc. dated January 16, 2019.


The approximate centre of the site using the NAD (North American Datum) 1983 convention is:


Latitude: 49° 15' 8.01" Longitude: 122° 45' 26.10"

May 1, 2019

Date Issued

Liliana Jerade





May 1, 2019 Date Issued

Eiliana Jerade For Director, Environmental Management Act

Schedule B

Requirements and Conditions

1.	Any changes in land, vapour, or water uses must be promptly identified by the responsible
	persons in a written submission to the Director. An application for an amendment or new
	Certificate of Compliance may be necessary. The uses to which this condition applies are
	described in Schedule C and in the site investigation documents listed in Schedule D.

May 1, 2019

Date Issued

Liliana Jerade

Schedule C

Substances and Uses

Substances remediated in soil for commercial land soil use:

To meet numeric-based remediation standards:

- chromium (CAS # 7440-47-3);
- and nickel (CAS # 7440-02-0).

May 1, 2019

Date Issued

Liliana Jerade

Schedule D

Documents

- Summary of Site Condition, prepared by Hemmera Envirochem Inc., dated March 2019;
- Protocol 6 Approval Request, Entire extent of contamination has not been delineated and/or remediated, 1579 Kingsway Avenue, Port Coquitlam, BC (the "Site") Western Portion, dated March 14, 2019;
- Stage 1 Preliminary Site Investigation Update, 1579 Kingsway Avenue, Port Coquitlam, BC, prepared by Hemmera Envirochem Inc., dated March 2019;
- Confirmation of Remediation, 1579 Kingsway Avenue, Port Coquitlam, BC, prepared by Hemmera Envirochem Inc., dated December 2018;
- Detailed Site Investigation, 1545 & 1575 Kingsway Avenue, Port Coquitlam, BC, prepared by Hemmera Envirochem Inc., dated November 2017;
- Stage 2 Preliminary Site Investigation, 1545 and 1575 Kingsway Avenue, Port Coquitlam, BC, prepared by Hemmera Envirochem Inc., dated June 2017;
- Stage 1 Preliminary Site Investigation Update, 1545 & 1575 Kingsway Avenue, Port Coquitlam, BC, prepared by Hemmera Envirochem Inc., dated October 2016; and,
- Stage 1 Preliminary Site Investigation, 1545 and 1575 Kingsway Avenue, Port Coquitlam, BC, prepared by Next Environmental Inc., dated February 2005.

Iay 1, 2019		
Pate Issued		